**DUE DATE** 

DIST

LYLE, J. L. MARTINEZ, L. A

NAGEL, FLE. NESTA. S. NORTH. K. PARKER, A. M. ROOGERS, A. D

SHELTON, D. C SPEARS, M. S.

TRICE, K. D. TUOR, N. R. WIEMELT, K. WILLIAMS, J.

Encubrish C

ACTION

CORRES CONTROL INCOMING LTR NO

RECEIVED

01049 RF03

Bill Owens, Gavernor

Douglas H Benevento, Executive Program ESPONDENCE

Dedicated to protecting and improving the Health and Invironment of the people of Colorado

4300 Cherry Creek Dr S Denver, Colorado 80246-1530 Phone (303) 692-2000

Laboratory and Radiation Services Division 8100 Lowry Blvd Denver, Colorado 80230-6928

TDD Line (303) 691-7700 Located in Glendale, Colorado

(303) 692 3090



of Public Health and Environment

BERARDINI. J. H BOGNAR, E. S. http://www.cdphe.state.co.us BROOKS, L BUTLER, L ROCKETT, G. A CROCKETT, G A
DECK, C, A
DECK, C, A
DEGENHART, K, R.
DIETER, T, J.
DIETERLE, S, E
FERRERA, D, W,
GIACOMINI, J, J.
LINDSAY, D, C.
LONG, J, W,
LYLE, J, L.

November 10, 2003

Mr Joe Legare Acting Assistant Manager for Environment and Stewardship U.S. Department of Energy, Rocky Flats Field Office 10808 Highway 93, Unit A Golden, CO 80403-8200

RE Closeout Reports for Building 367 and Trailers 121A, 334B, and 760A

Dear Mr Legare

The Colorado Department of Public Health and Environment, Hazardous Materials and Waste Management Division has reviewed the Closeout Reports for Building 367 and trailers 121A, 334B, & 760A, dated February 13, 2003 We appreciate being provided these Closeout Reports for our information.

As we have previously requested, Closeout Reports should identify all removal activity and include a map of the facility identifying the structures involved, those removed, and the location of remaining infrastructure and its condition Infrastructure includes all remaining materials and their location, and includes slabs, piers, footings, water pipes, gas lines, electrical conduits, dram lines, PWIs, sewer lines, etc. These maps are necessary for possible ER and/or future stewardship

The information provided for B367 does not specifically address the ultimate disposition of the concrete slab, only the "above grade building debris" Please provide information on the disposition of the concrete slab associated with B367

It is assumed, since not discussed, that the sewer lines associated with Trailer 760A were properly flushed as indicated in the Facility Disposition RSOP, which is supposed to be followed for all facilities

Revised Closeout Reports for both B367 and T760A should be provided to properly address these concerns

COR. CONTROL ADMN. RECORD

If you have any questions regarding this correspondence please contact me at (303) 692-3367 or David Kruchek at (303) 692-3328

Reviewed for Addressee Corres Control RFP

Steven H Gunderson

**RFCA Project Coordinator** 

Smcerely

Ref Ltr #

CC

Steve Tower, DOE Tım Rehder, EPA

Steve Nesta, KH

Administrative Records Building T130G

Cameron Freiboth, KH Dave Shelton, KH David Abelson, RFCLOG

NUI RECEIVL RECORDS CENT

DOE ORDER #

5400

DOCUMENT CLASSIFICATION REVIEW WAIVER PER CLASSIFIC. TION OFFICE

**ADMIN RECORD** 

IA-A-001804